



# Work Order

## WORK ORDER INFORMATION

**Work Order Name:** WO/70007HR2101/1

**Work Order Type:** Weatherization

**Audit Name:** Audit (88)

## CLIENT INFORMATION

**Client Name:**

**Address:**

**Client ID:** 70007HR2101

**Alt. Client ID:**

## AGENCY INFORMATION

**Agency:** HREC

**Agency Phone:** (931) 289-4101

**Address:** P.O Box 208  
Erin, TN 37061

**Fax:**

**Email Address:** lewis@hrec.org

**Agency Contact:** Adamson, James R

**Work Phone:** (615) 478-1355

**Cell Phone:** (615) 478-1355

**Email Address:** jamieadamson@rocketmail.com

**Company Name & License Number:** \_\_\_\_\_

**Contractor's Signature:** \_\_\_\_\_

## COMMENT

Work Order By: James Adamson

Blower Door 50 Pascals @ 8014 CFM's

House Age 1929 / 1180 SF

---

**Client Name:**

**Client ID:** 70007HR2101

**Alt. Client ID:**

### **Work Order**

**Work Order Name:** WO/70007HR2101/1

**Report Run On:** 5/13/2010

**DOE Weatherization Assistant**

**Version 8.5.0**

**Page 1 of 7**

## Measures

### Measure 1 Infiltration Redctn

### Components

Inspected

**Comment** Air Infiltration.

1. Build overhead door at top of stairwell with 3/4" birch plywood and stain to match existing wood. Existing handrail will have to be cut so door can meet joist band trim. Seal around perimeter of door with weather strip, and caulk all trim around door. Make door to hinge on left hand side, and include positive closure. Include R-19 batt over top of door.

Call 615-478-1355 with any questions about door specs.

2. Seal two old flue pipe thimbles inside home.

3. Adjust to make open and close better, weather-strip, and install door sweep on three exterior doors.

4. Caulk around interior of all windows with clear paintable caulk. Caulk where window meets trim and trim meets wall.

5. Seal plumbing penetrations with foam in following areas:

A. Kitchen Sink.

B. Bath Sink.

C. Seal Shower From Crawl With Rigid Foam Board and Mastic.

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	5			<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Other Detail</b>									
							<input type="text"/>	<input type="text"/>	<input type="text"/>
							<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Measure Sub Total:</b>							<b>Sub Total:</b>	<input type="text"/>	

**Field Notes:**

Client Name:

Client ID: 70007HR2101

Alt. Client ID:

**Work Order**

Work Order Name: WO/70007HR2101/1

Report Run On: 5/13/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 7

**Measure 2 Replace Htg. System****Components** HS1,HS2,HS2 (3)**Inspected**

**Comment** Include new pad with HVAC system. Contractor is responsible for all necessary connections for this installation. System will meet all local code requirements and manufacturer specifications.

Contractor will be responsible for sizing new unit to home.

#	Material / Labor	Description /Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Install Gas Package HVAC.	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Install Gas Package HVAC.	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Other Detail</b>							<input type="text"/>	<input type="text"/>	<input type="text"/>
							<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Measure Sub Total:</b>							<b>Sub Total:</b>	<input type="text"/>	

**Field Notes:**

**Measure 3 Attic Ins. R-38****Components** A1,A2**Inspected****Comment** A. One access will have to be cut to get to North side of home in attic.☐

B. The back side of the home can be reached through a small knee wall from attic. This will need to be blown first.

C. 21' 6" x 12' floor in attic will have to be dense packed. Removal of floor boards down middle of floor may be necessary to dense pack floor.

D. Include styrofoam baffles and plug void between top wall plate and baffle with fiberglass batt.

#	Material / Labor	Description /Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	920			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Insulation	Attic Insulation - Cellulose, Blown - R-38  This area is comment C.	SqFt	260			<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>							<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>							<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:							Sub Total: <input type="text"/>		

**Field Notes:****Measure 4 Floor Ins. R-19****Components** F1**Inspected****Comment** Most of this joist system is 24" centers, but the joist range from 4" - 8" joist.☐

#	Material / Labor	Description /Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1180					
Other Detail									
Measure Sub Total:							Sub Total:		

**Field Notes:**

Client Name:  
Client ID: 70007HR2101  
Alt. Client ID:

**Work Order**  
Work Order Name: WO/70007HR2101/1  
Report Run On: 5/13/2010

DOE Weatherization Assistant  
Version 8.5.0  
Page 4 of 7

**Measure 5 Wall Insulation****Components** WE1,WE2,WE3,WN  
1,WN2,WN3,WS1,W  
S2,WW1,WW2**Inspected****Comment** This home has wood siding, so include using wood plugs, and caulk, prime ,  
and paint all wood plugs to match existing white paint.☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1110			<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:****Measure 6 CO Monitor is Needed****Components****Inspected****Comment** Install c/o monitor in living room area.☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1			<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:**

Client Name:

Client ID: 70007HR2101

Alt. Client ID:

**Work Order**

Work Order Name: WO/70007HR2101/1

Report Run On: 5/13/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 7

**Measure 7 Fix Improper Venting (Clothes Dryer)****Components****Inspected**

**Comment** Install metal flex pipe on dryer and vent to exterior. Include exterior vent trim.  
Dryer sits on an exterior wall , so installation should be friendly.

☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1			<input type="text"/>	<input type="text"/>	<input type="text"/>

**Other Detail**

<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:****Measure 8 Unvented Space Heater****Components****Inspected**

**Comment** Remove unvented space heaters and cap off gas lines.  
One is in Kitchen / One is in Middle Bedroom.

☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Other	Remove Unvented Space Heater.	Each	2					

**Other Detail**

<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:**

Client Name:

Client ID: 70007HR2101

Alt. Client ID:

**Work Order**

Work Order Name: WO/70007HR2101/1

Report Run On: 5/13/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 7

Measure 9 Vapor Barrier Needed (Basement/Crawlspace)				Components			Inspected		
Comment									
				Estimated			Actual		
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	SqFt	1180			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	SqFt	1180			<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail							<input type="text"/>	<input type="text"/>	<input type="text"/>
							<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:							Sub Total:		<input type="text"/>
Field Notes:									
Work Order Grand Total:							Grand Total:		<input type="text"/>